MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents
		Number	Length	Breadth	Depth	
1	2	3	4	5	6	7
	certificate:-					
	1) certified that contractor has done the work satisfactory.					
	2) certified that there is no due work from contractor side.					
	3) Ravi. N.K. 31/12/2014.					
						31/12/14
						ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ ಎಸ್.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು

Audited and admitted for Rs. 1498375=00

Passed by Cheque for Rs. 1406974=00

(.....)

by adjustment Rs. 91401=00

Accounts Superintendent — Executive Engineer

B.B.M.P., Hegganahalli Division

25/5/15

REMENT BOOK

ber	Dimensions Length 4	Breadth 5	Depth 6	Contents 7	Ref to Meas
s done the work Satisfactory.					
e work from Contractor side.					
31/12/14					
ಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು					
ಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ					
ಕತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ					
ಸಿ.ಎಂ ರಸ್ತೆ, ರವೀಂದ್ರನಗರ, ಬೆಂಗಳೂರು					
25/5/15					

M. A. R. 57 (Rule 116)
Measurement Book

No. B

1st & final.

BR 825/9.1.2015 178861

Work Maintainance of bore well at Abbigere and Medarahalli in ward no-12 From ..... To .....
Shettyhalli sub-Division
Contractor of nature of Agency S. prakash Sc:- 012-14-000009 Est cost:- 15.0 lakh
Commencement of work No EE/DD/WO/258/13-14 Dt:-15/2/14.

Full description, etc, of work 2	Number 3	Dimensions Length 4	Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
		Recorded on 31/12/2014.				
Repair to Motor Rewinding of Submersible pumpsets with copper insulation wire of suitable gauge as per IS specification with guarantee of 6 months 7.5 HP.						
7.5HP						
) Abbigere Near Lakshmi temple	1 No				= 1 NO	
) Abbigere Shivananjappa layout pipe line Road	1				= 1 NO	
) Abbigere patelappa layout 1st cross	1				= 1 NO	
) Abbigere Janatha colony pump house	1				= 1 NO	
					4 Nos @ 3822=50	Rs:- 15290=00

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Re
		Number	Length	Breadth	Depth		Me
1	2	3	4	5	6	7	
J-2	Repairs to motor: Rewinding of submersible pumpsets with copper insulation wire of suitable guage as per ISI specification with gurantee of 6 months 10 HP. 10 HP.						
	1) Shettyhalli Krishnanagara	1				= 1 No	
	2) Abbigere chowdappa layout Neare Jayram house	1				= 1 No	
	3) Shettyhalli Janatha colony. Near venugopal house	1				= 1 No	
	4) Abbigere S.M.R. Layout	1				= 1 No	
	5) Shettyhalli Near Saraswathi School	1				= 1 No	
	6) Abbigere Karekalle Near Nagaraj house	1				= 1 No	

.....
Work .....
ontractor of nature of Agency.....
mmencement of work.....

Full description, etc, of work
2
Shettyhalli Byraweshwara nagara 7th cross
Abbigere Someshwara temple
Shettyhalli Adarshanagar
Abbigere Near bus Stop
Shettyhalli Royal Avenue Road
Abbigere venkateshwara layout 8th cross
Shettyhalli Vigneshwara layout

back to

about 3- 4%
es not readily c
t 96- 97% c
ory pigment

826

Connt 825
from 48

ASUREMENT BOOK

Dimensions				Contents	Re to Mea
Number 3	Length 4	Breadth 5	Depth 6	7	
ing of submersible pumpsets wire of suitable guage as per rantee of 6 months 10 HP.					
1				= 1 NO	
1				= 1 NO	
				= 1 NO	
1					
1				= 1 NO	
1				= 1 NO	
1				= 1 NO	
1				= 1 NO	

57 (Rule 116)
rement Book

No. B

178862

work ..... To .....

Contractor of nature of Agency.....

ommencement of work.....

Full description, etc, of work 2	Number 3	Dimensions Length 4	Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
Shettyhalli Byrawesh wara	1				= 1 NO	
nagara 7th cross	1				= 1 NO	
Abbigere Someshwara temple	1				= 1 NO	
) Shettyhalli Adarshanagar	1				= 1 NO	
) Abbigere Near bus Stop	1				= 1 NO	
1) Shettyhalli Royal Avenue Road	1				= 1 NO	
2) Abbigere venkateshwara layout 8th cross	1				= 1 NO	
3) Shettyhalli Vigneshwara layout	1				= 1 NO	

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents	Re
		Number	Length	Breadth	Depth		
1	2	3	4	5	6	7	
	14) Abbigere unique School	1 NO				= 1 NO	
	15) Near Shettyhalli Near Military house	1 NO				= 1 NO	
	16) Abbigere Govt school	1 NO				= 1 NO	
	17) Nandanamagara 2nd cross	1 NO				= 1 NO	
	18) Gate Palya Railway gate	1 NO				= 1 NO	
	19) Paschim county 2nd cross	1 NO				= 1 NO	
	20) Babanna layout.	1 NO				= 1 NO	
						20 Nos	
						@ 4785=00	
							N. 95700

Verified
EE(D3)/12

Ma ..... ork .....
ontractor of nature of Agency.....
nmencement of work.....

Full description, etc, of work
2
epairs to motor rew
with copper insulatio
IS1 Specification with g
Abbigere Marathi layout
ear Mahesh house
Shettyhalli Near Metro
bakery
Abbigere Surya enclave
Abbigere paschim county
1st Main

ASUREMENT BOOK

	Dimensions				Contents	Ref to Meas
	Number 3	Length 4	Breadth 5	Depth 6	7	
	1 NO				= 1NO	
...ayt	1NO				= 1NO	
	1NO				= 1NO	
...ss	1NO				= 1NO	
...c	1NO				= 1NO	
...ss	1NO				= 1NO	
	1NO				= 1NO	
					20 NOS	
					@ 4785=00	Rs. 95700=
...3/12						

M. A. R. 57 (Rule 116)
Measurement Book

No. B

178863

.....
Work ..... From ..... To .....
Contractor of nature of Agency.....
ommencement of work.....

Full description, etc, of work 2	Dimensions Number 3	Length 4	Breadth 5	Depth 6	Contents 7	Reference to last Measurement 8
Repairs to motor rewinding of submersible pumpsets with copper insulation wire of suitable guage as per ISI specification with gurantee of 6 months 12 HP						
1 Abbigere Marathi layout Near Mahesh house	1				= 1NO	
Shettyhalli Near Metro bakery	1				= 1NO	
Abbigere Suryaenclave	1				= 1NO	
Abbigere paschim county 1st Main	1				= 1NO	
					4 NOS	Rs:- 23420=00
					@ 5855=00	

Verified
EE(D)
31/12

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents
		Number	Length	Breadth	Depth	
1	2	3	4	5	6	7
	ON/OFF energy cons breaking capacity of 10k and complete wiring as required.	3 with Short Circuit				
	1) 7.5HP	4x1				= 4.0 Nos
	2) 10.0 HP	20x1				= 20.0 Nos
	3) 12.5 HP	4x1				= 4.0 Nos
		1498182=00				28.0 Nos
	Raei.N.K. 31/12/14 Total. Rs	1498182-00				@ 1005-00 Rs. 28
	Certificate	TOTAL - 1489582-00				
	1) certified that contractor has done the work satisfactory.					
	2) certified that there is no due work from contractor side					
	Raei.N.K 31/12/2014					

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶೆಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

back to

lled

MEASUREMENT BOOK

ork	Dimensions				Contents	
	Number 3	Length 4	Breadth 5	Depth 6	7	
Cross	3 with Short Circuit					
of 10k	and Complete Wiring as					
	4×1				=4.0 Nos	
	20×1				=20.0 Nos	
	4×1				=4.0 Nos	
	1498182=00				28.0 Nos	
					@ 1005-00	
					Rs.-2814	
al. Rs	1498182-00					
TOTAL	1489582-00					
ractor has done the work satisfactory.						
re is no due work from contractor side						
2014						

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ಶಿಟ್ಟಿಹಳ್ಳಿ ಉಪವಿಭಾಗ, ದಾಸರಹಳ್ಳಿ ವಲಯ
ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ

M. A. R. 57 (Rule 116)
Measurement Book

No. B

178875

Work ..... From ..... To .....
Contractor of nature of Agency .....
Commencement of work ..... Puttaraju. A ..... JC:i-012-15-000016.

Providing improvements to road & drains at Shyhagiri layout balance portion at Attiere near tank in Wardno-12 SSD
NO EE/DD/NO/248/14-15 Di-18/2/15.

Full description, etc, of work 2	Dimensions				Contents	Reference to last Measurement
	Number 3	Length 4	Breadth 5	Depth 6	7	8
Earth work excavation by manual means in hard soil.	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 19.0	× 0.70	× 0.70	= 18.62 cum	
	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 30.0	× 0.70	× 0.70	= 29.40 cum	
	1	× 29.0	× 0.70	× 0.70	= 28.42 cum	

MEASUREMENT BOOK

Date	Full description, etc, of work	Dimensions				Contents
		Number	Length	Breadth	Depth	
1	2	3	4	5	6	7
	necessary bolts nuts washers & wiring etc.) complete with AC-3 rating and as per IS-13947-25 Amps					
	1) 7.5HP.	4×1				= 4.0 Nos
	2) 10.0 HP	20×1				= 20.0 Nos
	3) 12.5 HP.	4×1				= 4.0 Nos
						28.0 Nos
						@ 925=00 Rs. 25
I-47	Supplying and fixing porcelain fuse channel with cut out on existing wooden panel necessary nuts bolts & washers etc.) complete 32 Amps.					
	1) 7.5 HP	4×1				= 4.0 Nos
	2) 10.0 HP	20×1				= 20.0 Nos
	3) 12.5 HP	4×1				= 4.0 Nos
						28.0 Nos
						@ 100=00 Rs. 28

Verified
EE(D) 1/12.

1498182=00 and admitted for Rs. 1489
067 93= 1398717=0
ssed by Cheque for Rs.
Work
91389=00
ontractor of nature of Agency
by adjustment Rs
mmencement of work

Full description, etc, of work
Accounts Superintendent
B.M.P., Heggenahalli Divis

Supplying and fixing
Ac voltmeter and
1) 7.5 HP.
2) 10.0 HP.
3) 12.5 HP.

Supplying and fixing
on existing MCB distr
fixing materials an

MEASUREMENT BOOK

	Dimensions				Contents	
	Number 3	Length 4	Breadth 5	Depth 6	7	R
s washers & wiring etc.) rating and as per IS-13947-25 Amps						
	4x1				= 4.0 Nos	
	20x1				= 20.0 Nos	
	4x1				= 4.0 Nos	
					28.0 Nos	
ng Porcelain fuse channel with wooden Panel necessary nuts etc.) complete 32 Amps.					@ 925=00 Rs- 259	
	4x1				= 4.0 Nos	
	20x1				= 20.0 Nos	
	4x1				= 4.0 Nos	
					28.0 Nos	
					@ 100=00 Rs- 280	

EE(D)1/12

1498182=0 ~~1489582=0~~
and admitted for Rs. .....
406793=~~1398717=0~~
ssed by Cheque for Rs. .....
91389=~~90865=0~~
Contractor of nature of Agency ..... From
by adjustment Rs .....
mmencement of work 25/5/15

Executive Engineer
B.M.P., Hogganahalli Division

Accounts Superintendent

M. A. R. 57 (Rule 116)
Measurement Book

lo. B

178874

Full description, etc. of work	Dimensions				Contents	Reference to last Measurement
	Number 3	Length 4	Breadth 5	Depth 6	7	8
s Supplying and fixing and wiring 0 to 600 volts 96x96mm Ac voltmeter and existing panel wood board						
1) 7.5 Hp.	4x2				= 8.0 Nos	
2) 10.0 Hp.	20x2				= 40.0 Nos	
3) 12.5 Hp.	4x2				= 8.0 Nos	
					76.0 Nos	
					@ 430=00 Rs- 32680=00	
49 Supplying and fixing maintenance Circuit breakers on existing MCB distribution boards using necessary fixing materials and c type curve indicator						

~~4080/-~~
32680